


Step 1: Mount the end caps for the back standoff to the hood using self-tapping sheet metal screws provided. Screw through the end cap flanges into the flanges on the hood.




Step 3: Attach the back standoffs to the wall using screws appropriate for the wall. Screw through the flanges of the standoff into the wall. If standoff mounts against another hood, use the procedure from steps 1 and 2 for the second hood.



Step 2: Place the back standoff horizontal filler piece into place. Mount the filler piece using self-tapping sheet metal screws provided. Screw through the filler piece flanges into the studs on the back side of the hood. Do not penetrate into the capture area. Once complete, no screws should be visible from the outside of the hood.





Material:	18 Ga	Stainless	Steel
Blank Size:N/A			
Waight: N	J/A lha		

CONFIDENTIAL

Part Number: See Table
MACOLA Number: N/A
Drawing Name: Back Standoff Assembled
Drawn By: JTS
Parent Assembly: ND-2

Sheet: 1 of 1

Dimensions are in Inches.

Standard Tolerances are: Fractions: ±1/16
Decimal: .XX ±.05
.XXX ±.015